

## **Revision: 1** Date: 21<sup>st</sup> July,2014

# Schedule - 16

### Office Equipments (Printers, Scanners, Copiers, Fax Machines and Multi <u>Function Devices</u>)

#### 1. <u>Scope</u>

- (i.)This schedule specifies the energy labeling requirements for office equipment namely copiers, printers, fax machines, scanners and multi-function devices for office automation and similar use.
- (ii.)This schedule is for only single phase office equipment (printers, scanners, copiers, fax machines and multi-function devices) which operate at the standard voltage and frequency range specified by the relevant Indian Standards and the Indian Electricity Rules 1956.
- (iii.)Office equipment (Printers, Scanners, Copiers, Fax Machines and Multi-Function Devices) shall meet all the requirements specified in this schedule for the purpose of labeling.
- (iv.)This Standard has been prepared on the basis of Energy Star specification for imaging equipment<sup>1</sup> developed by US Environment Protection Agency (EPA).

#### 2. <u>Exclusions to the Scope</u>

The following products are not a part of the Schedule

- a. <u>Production Printing Machines</u> A product whose primary function is to print very High Volumes & at High Speed ranging from 55 ppm onwards. It is a Color, Black & White and Custom Color cut sheet and continuous feed production printers and digital presses for large volume transaction bill printing, graphic arts, and for commercial printing and publishing.
- b. <u>Large Format Printers</u> Products designed for A2 media and larger, including those designed to accommodate continuous-form media greater than or equal to 406mm wide. These products are also capable of printing on standard size or small format media but are primarily used for large engineering, manufacturing, architecture and construction companies who require large prints of designs of products, 3D Rendering etc. Also widely

<sup>&</sup>lt;sup>1</sup> <u>http://www.energystar.gov/ia/partners/product\_specs/program\_reqs/Imaging\_Equipment\_Program\_Requirements.pdf</u>



used for indoor display graphics applications. The Large Format Printers are also popularly known as Wide Format Printers.

3. **Definitions:** The definitions of the various terms used in this schedule is as follows:

### A) Product Types:

**3.1. Office Printer:** A product whose primary function is to generate hard-copy output from electronic input. A printer is capable of receiving information from single-user or networked computers, or other input devices (e.g., digital cameras). This definition is intended to cover products that are marketed as printers, and printers that can be field-upgraded to meet the definition of an MFD.

**3.2.** Scanner: A product, whose primary function is to convert hard copy originals into electronic images that can be stored, edited, converted, or transmitted, primarily in a personal computing environment. This definition is intended to cover products that are marketed as scanners.

**3.3.** Copier: A product whose sole function is to produce hard copy duplicates from hard copy originals. This definition is intended to cover products that are marketed as copiers, and upgradeable digital copiers (UDCs).

**3.4.** Facsimile (Fax) Machine: A product whose primary functions are (1) to scan hard copy originals for electronic transmission to remote units, and (2) to receive electronic transmissions for conversion to hard copy output. A fax machine may also be capable of producing hard copy duplicates. Electronic transmission is primarily over a public telephone system, but may also be via a computer network or the Internet. This definition is intended to cover products that are marketed as fax machines.

**3.5. Multifunction Device (MFD):** A product that performs two or more of the core functions of a Printer, Scanner, Copier, or Fax Machine. An MFD may have a physically integrated form factor, or it may consist of a combination of functionally integrated components. MFD copy functionality is considered to be distinct from single-sheet convenience copying functionality sometimes offered by fax machines. This definition includes products marketed as MFDs, and "multi-function products" (MFPs).

#### **B)** Marking Technologies:

**3.6.** Direct Thermal (DT): A marking technology characterized by the burning of dots onto coated print media that is passed over a heated print head. DT products do not use ribbons.



**3.7.** Dye Sublimation (DS): A marking technology characterized by the deposition (sublimation) of dye onto print media as energy is supplied to heating elements.

**3.8.** Electro-photographic (EP): A marking technology characterized by the illumination of a photoconductor in a pattern representing the desired hard copy image via a light source, development of the image with particles of toner using the latent image on the photoconductor to define the presence or absence of toner at a given location, transfer of the toner to the final print media, and fusing to cause the hard copy to become durable. For purposes of this specification, Color EP products simultaneously offer three or more unique toner colors, while Monochrome EP products simultaneously offer one or two unique toner colors. This definition includes Laser, Light Emitting Diode (LED), and Liquid Crystal Display (LCD) illumination technologies.

**3.9.** Impact: A marking technology characterized by the formation of the desired hard copy image by transferring colorant from a "ribbon" to the print media via an impact process. This definition includes Dot Formed Impact and Fully Formed Impact.

**3.10.** Ink Jet (IJ): A marking technology characterized by the deposition of colorant in small drops directly to the print media in a matrix manner. For purposes of this specification, Color IJ products offer two or more unique colorants at one time, while Monochrome IJ products offer one colorant at a time. This definition includes Piezo-electric (PE) IJ, IJ Sublimation, and Thermal IJ. This definition does not include High Performance IJ.

**3.11. High Performance IJ:** An IJ marking technology that includes nozzle arrays that span the width of a page and/or the ability to dry ink on the print media via supplemental media heating mechanisms. High-performance IJ products are used in business applications usually served by electro-photographic marking products.

**3.12.** Solid Ink (SI): A marking technology characterized by ink that is solid at room temperature and liquid when heated to the jetting temperature. This definition includes both direct transfer and offset transfer via an intermediate drum or belt.

**3.13.** Thermal Transfer (TT): A marking technology characterized by the deposition of small drops of solid colorant (usually colored waxes) in a melted/fluid state directly to print media in a matrix manner. TT is distinguished from IJ in that the ink is solid at room temperature and is made fluid by heat.

### C) Operational Modes:

#### 1. On Mode:

a) Active Mode: Definition as defined in Clause 3.8 of IEC 62301 : 2011



**b) Ready State**: The power state, in which a product is not producing output, has reached operating conditions, has not yet entered into any lower-power Modes, and can enter Active State with minimal delay. All product features can be enabled in this state, and the product is able to return to Active State by responding to any potential inputs, including external electrical stimulus (e.g., network stimulus, fax call, or remote control) and direct physical intervention (e.g., activating a physical switch or button).

2. Off Mode: Definition as defined in Clause 3.5 of IEC 62301 : 2011

**3. Sleep Mode:** A reduced power state that a product enters either automatically after a period of inactivity (i.e., Default Delay Time), in response to user manual action (e.g., at a user-set time of day, in response to a user activation of a physical switch or button), or in response to external electrical stimulus (e.g., network stimulus, fax call, remote control).

a. For products evaluated under the TEC test method, Sleep Mode permits operation of all product features (including maintenance of network connectivity), albeit with a possible delay to transition into Active State.

b. For products evaluated under the OM test method, Sleep Mode permits operation of all product features considered Primary Function adders, albeit with a possible delay to transition into Active State.

e) Standby: Definition as defined in Clause 3.6 of IEC 62301:2011

For Office Equipments addressed by this schedule, the "Standby" Mode usually corresponds to Off Mode, but may correspond to Ready State or Sleep Mode. Hence whichever is the lowest power state among Ready, Sleep, Auto-off and Off state shall be considered as the standby power mode for office equipments under this schedule. A product cannot exit Standby and reach a lower power state unless it is physically disconnected from the main electricity supply as a result of manual manipulation.

#### **D) Media Format:**

**1. Large Format:** Products designed for A2 media and larger, including those designed to accommodate continuous-form media greater than or equal to 406 mm wide. Large-format products may also be capable of printing on standard-size or small-format media.

**2. Standard Format:** Products designed for standard-sized media (e.g., Letter, Legal, Ledger, A3, A4, B4), including those designed to accommodate continuous-form media between 210 mm and 406 mm wide. Standard-size products may also be capable of printing on small-format media.



**3. Small Format:** Products designed for media sizes smaller than those defined as Standard (e.g.,A6, 4"x6", microfilm), including those designed to accommodate continuous-form media less than 210 mm wide.

**4.** Continuous Form: Products that do not use a cut-sheet media format, and that are designed for applications such as printing of bar codes, labels, receipts, banners, and engineering drawings. Continuous form products can be of small, standard, or large format.

#### **Others:**

**1. Marking Engine:** The fundamental engine of an imaging product that drives image production. A marking engine relies upon functional adders for communication ability and image processing. Without functional adders and other components, a marking engine cannot acquire image data for processing and is non-functional.

**2.Base Product:** The most fundamental configuration of a particular product model, which possesses the minimum number of functional adders<sup>2</sup> available. Optional components and accessories are not considered part of a base product.

**3. Family of models:** Family of models is the range of models of one particular brand, to which a single set of test reports is applicable and where each of the models has the same relevant physical characteristics, energy consumption, and energy efficiency rating and performance characteristics. The term 'model' is synonymous with 'family of models'. For office equipment, acceptable variations within a product family include:

- Color
- Housing
- Input or output paper-handling accessories, or
- Any of the functional adders.

**4. Variant:** A model variant is an alternative version of a model which has the same sales specification and the same model number or other form of designation as another version of the model, and offers the same performance except that it has different standby mode power consumption.

**5. Model Number:** A unique marketing name that applies to a specific hardware/software configuration that is either predefined, or a configuration that is selected by the customer.

6. **Model Name:** A marketing name that includes reference to both the office equipment model family number, a short description of the product, or branding references.

<sup>&</sup>lt;sup>2</sup> Functional Adders or Add On: Data and network interface that adds functionality to the marking engine of an imaging equipment product and provides a power allowance when qualifying products according to the test method.



#### 7. Pre-qualification Requirements

A. Commercially-available office equipments that meet one of the Product Type definitions in Section 2 and are capable of being powered from

(1) a wall outlet,

(2) a data or network connection, or

(3) both a wall outlet and a data or network connection, are eligible for BEE STAR qualification.

B. The products shall confirm to the requirements of relevant Indian standards for both safety and performance requirements to participate in BEE STAR labeling program.

C. To qualify for the BEE Star labeling, the office equipment shall satisfy the requirements as specified in the clause 3.3 & 3.4 under 'Qualification Criteria' of ENERGY STAR Program Requirements for Imaging Equipment.

**8. Standby Power Requirements:** Standby Mode power, which is the lesser of the Ready Mode Power, Sleep Mode Power, and Off Mode Power, as measured in the test procedure, shall be less than or equal to 1 W for all Operational Mode (OM) products .

9. **Testing Procedure:** To qualify as BEE Star labeled product, the units must be tested according to test protocol outlined in **Appendix A** of this schedule. Manufacturers are required to perform tests and self-certify those models that meet the BEE Star Label requirements:

a. The test results must be reported to BEE.

b. The test results must be reported in the format outlines in Appendix B along with the lab test report

#### Detailed Test Procedures is defined in Appendix A.

10. **Tolerance limits:** There is **no tolerance in the energy consumption criteria** for obtaining the BEE label. All tested products must meet the maximum threshold for OM and TEC products. The scope for manufacturing tolerance and other variations shall be accounted for while applying for the BEE Star label.

11. Label Design and Manner of Display: The label design and manner of display will be as defined as follows:

 $\succ$  For initial one year from date of the launch of the program, manufacturers can affix the BEE Star label either on the carton box or on the products itself.

➤ After the period of one year, the committee will again review the prospects of the decision to make it mandatory to affix label on both the carton box and the product or not. Sample Label is given in Annexure 1.

#### **12. Labeling related fees:**

Refundable security deposit payable for registration of every company/firm for BEE Standard & Labeling program is Rs.100000/- (Rupees One Lakh), which is Rs. 25000/-



(Rupees Twenty Five Thousand) for SSI industries, provided they upload their duly valid SSI certificate on BEE's e-filling portal.

- Registration fee payable on each application for authority to affix labels is Rs.1000/-(Rupees One Thousand Only).
- Labeling fee for affixation of label on each piece of qualified product is 0.03% of the product MRP declared by the user of the label (manufacturer / trader / importer) at the time of product-model registration under each equipment category.
- Registration fee payable on each application for renewal of authority to affix labels is Rs.500/- (Rupees Five Hundred Only).

#### **13.**Future Specification Revisions

BEE reserves the right to revise the schedule should technological and/or market changes affect its usefulness to consumers or industry or its impact on the environment. In keeping with current policy, revisions to the schedule will be discussed with stakeholders. In the event of a schedule revision, please note that BEE qualification is not automatically granted for the life of a product model. To qualify as Star labeled product, a product model must meet the BEE's standard in effect on the model's date of manufacture.



#### **APPENDIX A:**

#### Test Procedure for Determining the Standby Power Consumption in Office Equipments

#### 1. OVERVIEW

The following test method shall be used for determining product compliance with requirements in the BEE STAR Eligibility Criteria for **Office Equipment**.

#### 2. **DEFINITIONS**

Unless otherwise specified, all terms used in this document are consistent with the definitions given in the section 3 of this schedule.

➤ Unit Under Test (UUT): The specific sample of a Representative Model undergoing measurement, which includes the base product and any accessories packaged with it.

#### 3. TEST SETUP

A. <u>AC Input Power:</u> Products intended to be powered from AC mains shall be connected to a voltage source appropriate for the intended market.

Products shipped with external power supplies (EPSs) shall first be connected to the EPS and then to the voltage source specified in Table 1.

Test Voltage:	230 (± 1%) Volts AC, 50 Hz (± 1%)
	<i>Note:</i> For products rated for > 1.5 kW maximum power, the voltage range is $\pm 4\%$
<b>Total Harmonic Distortion</b>	< 2% THD ( $< 5%$ for products which are rated for $>$
(THD) (Voltage):	1.5 kW maximum power) <sup>3</sup>
Ambient Temperature:	27±5°C
<b>Relative Humidity:</b>	10 - 80 %

#### **Table 1: Test Conditions**

#### B. Low-voltage DC Input Power:

1) Products may only be powered with a low-voltage DC source (e.g., via network or data connection) if the DC source is the only acceptable source of power for the product (e.g., no AC plug or EPS is included with the product).

Schedule for Office Equipments (Printers, Scanners, Copiers, Fax Machines and Multi Function Devices)

<sup>&</sup>lt;sup>3</sup> IEC 62301



2) Products powered by low-voltage DC shall be configured with an AC source of the DC power for testing (e.g., an AC-powered USB hub).

3) Reported UUT power shall be equal to the AC power consumption of the low-voltage DC source with the UUT as the load, minus the AC power consumption of the low-voltage DC source with no load (PS), as measured per section 5 of this procedure.

C. <u>Ambient Temperature:</u> Ambient temperature shall be 27±5°C.

**Note:** For a initial period of one year from the date of revision of this schedule (ie., date of revision 1), the ambient temperature shall be followed as  $23\pm5^{\circ}$ C and thereafter ambient temperature conditions shall be followed as  $27\pm5^{\circ}$ C.

- D. <u>Relative Humidity:</u> Relative humidity shall be from 10% to 80%.
- E. <u>Power Meter:</u> Power meters shall possess the following attributes:

1) Minimum Frequency Response (Recommended): 3.0 kHz

2) Minimum Resolution:

- i) 0.01 W for measurement values less than 10 W;
- ii) 0.1 W for measurement values from 10 W to 100 W;
- iii) 1 W for measurement values from 100 W to 1.5 kW; and
- iv) 10 W for measurement values greater than 1.5 kW.

v) Measurements of accumulated energy should have resolutions which are generally consistent with these values when converted to average power. For accumulated energy measurements, the figure of merit for determining required accuracy is the maximum power value during the measurement period, not the average, since it is the maximum that determines the metering equipment and setup.

F. Measurement Accuracy:

1) Measurements made with these procedures shall in all cases have an accuracy of 5% or better, though manufacturers will usually achieve better than this. Test procedures may specify greater accuracy than 5% for some measurements. With knowledge of the power levels of current imaging products and the meters available, manufacturers can calculate the maximum error based on the reading and the range utilized for the reading.

- 2) For measurements of 0.50 W or less, the required accuracy is 0.02 W.
- G. <u>Time Measurement:</u> Time measurements may be performed with an ordinary stopwatch with resolution of at least 1 second.
- H. Paper Specifications:



1) The Paper used while testing the Office Equipments (Printers, Scanners, Copiers, Fax Machine and Multi Function Devices) shall be in accordance with Table 2.

2) Large, small, and continuous format products shall be tested using any compatible paper size.

#### Table 2: Paper Size and Weight Requirements

Market	Paper Size	Basis Weight (g/m²)
India	A4	80

#### 4. LOW-VOLTAGE DC SOURCE MEASUREMENTS FOR ALL PRODUCTS

1) Connect the DC source to the power meter and relevant AC supply as specified in Table 1.

2) Verify that the DC source is unloaded.

3) Allow the DC source to warm up for a minimum of 30 minutes.

4) Measure and record the unloaded DC source power (PS) according to IEC 62301 Ed. 1.0.

#### 5. PRE-TEST UUT CONFIGURATION FOR ALL PRODUCTS

#### 5.1. General Configuration

A) <u>Product Speed for Calculations and Reporting:</u> The product speed for all calculations and reporting, shall be the highest speed as claimed by the manufacturer as per the following criteria, expressed in images-per-minute (ipm) and rounded to the nearest integer:

1) In general, for Standard-size products, a single A4 or 8.5" x 11" sheet printed/copied/scanned on one side in a minute is equal to one image-per-minute (ipm)

2) For all products, the product speed shall be based on:

i) The manufacturer-claimed print speed, unless the product cannot print, in which case,
ii) The manufacturer-claimed copy speed, unless the product cannot print or copy, in which case,
iii) The manufacturer-claimed scan speed.

3) For non-continuous-form products the product speed shall be calculated per Table 4. If the maximum claimed speeds differ when producing images on A4 or 8.5" x 11" paper, the higher of the two shall be used.



# Table 3: Calculation of Product Speed for Standard, Small, and Large FormatProducts4

Media Format	Media Size	Product Speed, s (ipm) Where: s <sub>p</sub> is the maximum claimed monochrome speed in pages-per- minute when processing the given media	
Standard	8.5" x 11"	Sp	
	A4	Sp 0.25	
Small	4" x 6"	0.25 x sp	
	A6	0.25 x s <sub>p</sub>	
Large	A2	4 x s <sub>p</sub>	
	A0	16 x sp	

4) For continuous-form products, product speed shall be calculated per Equation 1

#### Equation 1: Calculation of Product Speed

s = 16 wsL

Where:

- •s is the product speed, in images per minute (ipm),
- •*w* is the width of the media, in meters (*m*),
- $\bullet$ *s*<sub>L</sub> is the maximum claimed monochrome speed, in length-meters- per-minute.

B) Color: Color-capable products shall be tested making monochrome images unless incapable of doing so.

C) Network Connections: Products that are capable of being network-connected as-shipped shall be connected to a network.

5) The type of network connection (or other data connection if not capable of being networked) is at the discretion of the manufacturer, and the type used shall be reported.

#### 5.2. Configuration for Fax Machines

A) Fax machines need not be connected to a telephone line unless the telephone line is necessary for performing the test.

<sup>&</sup>lt;sup>4</sup> ENERGY STAR Program Requirements for Imaging Equipment



B) Unless sending jobs via phone line, originals may be placed in the document feeder before the test begins.

1) Products without a document feeder may make all images off a single original placed on the platen.

2) Fax machines shall be tested with one image per job.

#### 6. PRE-TEST UUT INITIALIZATION FOR ALL PRODUCTS

A) Prior to the start of testing, the UUT shall be initialized as follows:

1) Set up the UUT per the instructions in the Manufacturer's Instructions or documentation.

i) Accessories such as paper source and finishing hardware that are intended to be installed or attached by the end-user shall be installed; however, their use in the test is at the manufacturer's discretion (e.g., any paper source may be used).

2) Connect the UUT to its power source.

3) Power on the UUT and perform initial system configuration, as applicable. Verify that default delay times are configured according to product specifications and/or manufacturer recommendations.

i) <u>Product Speed for Testing</u>: The product shall be tested with speed settings in their default as-shipped configuration.

ii) <u>Auto-off for OM Products</u>: If a product has an Auto-off Mode enabled as shipped, it shall be **enabled** prior to performing the test.

<u>iii) Auto-off for TEC Products:</u> If a printer, digital duplicator or MFD with print-capability, or fax machine has an Auto-off capability and it is enabled as shipped, it shall be **disabled** prior to the test.

4) User-controllable anti-humidity features may be turned off or disabled for the duration of testing.

5) Let the UUT sit for at least 15 minutes, or until it has completed initialization and is ready for use.

6) For products designed to operate on battery power when not connected to the mains, the battery shall be either:

i) Removed from the product; or



ii) Fully charged for at least 24 hours before beginning the test and left in place for the test.

#### 7. Test Methods

The office equipment covered under this schedule shall follow the test methods as mentioned in Table 4:

Table 4: Test methods for Office Equipments

Product Type	Media Format	Marking Technology	Test Method
Copiers	Standard	DT, DS, EP, SI, TT	TEC
Copiers	Large	DT, DS, EP, SI, TT	OM
Fax Machine*	Standard	IJ	ОМ
	Standard	DT, DS, EP, High performance IJ, SI, TT	TEC
Multi Function Devices (MFDs)	S will will w	IJ	ОМ
(1125)	Large	DT, DS, EP, IJ, SI, TT	ОМ
	Standard	DT, DS, EP, SI, TT, High performance IJ	TEC
Printers	Sundard	Impact, IJ	ОМ
	Large or Small	DT, DS, EP, Impact, IJ, SI, TT	ОМ
Scanners	All	N/A	OM

\* Fax Machine with Ink-jet marking technology is only covered under the scope of this schedule.

#### 7.1. Measurement Procedures

7.1.1 For the equipments follows Operational Mode tests: Measurement of standby power shall be conducted according to Table 5, subject to the following provisions:

1) All power consumption figures shall be recorded in watts (W) in accordance with IEC 62301, unless otherwise specified in this document.

2) <u>Confidence Level or Accuracy</u>: The accuracy requirement for this OM test procedure is 2% for all measurements except for Ready power, where it is 5%. The 2% figure is consistent with IEC 62301.



3) <u>Service/Maintenance Modes:</u> Service/maintenance modes (including color calibration) generally should not be included in measurements. Any adaptation of the procedure needed to exclude such modes that occur during the test shall be noted.

Ste	Initial	Action(s)	Record	Unit of
р	State			Measure
1	Off	Plug the unit into meter. Turn on unit. Wait until unit indicates it is in Ready Mode.		
2	Ready	Print, copy, or scan a single image.		
3	Ready	Measure Ready power.	Ready power, <i>P<sub>READY</sub></i>	Watts (W)
4	Ready	Wait and measure default delay-time to Sleep.	Sleep default- delay time, <i>t</i> SLEEP	Minutes (min)
5	Sleep	Measure Sleep power.	Sleep power, P <sub>SLEEP</sub>	Watts (W)
6	Sleep	Wait and measure default delay time to Auto-off. (Disregard if no Auto-off Mode)	Auto-off default- delay time	Minutes (min)
7	Auto off	Measure Auto-off power. (Disregard if no Auto-off Mode)	Auto-off power P <sub>AUTO</sub> -OFF	Watts (W)
8	Auto off	Manually turn device off and wait until unit is off. (If no manual on-off switch, note and wait for lowest-power Sleep state).		
9	Off	Measure Off power. (If no manual on-off switch, note and measure Sleep Mode power).	Off power P <sub>OFF</sub>	Watts (W)

### Table 5: Testing procedure Operational Mode Products

Notes:



- Step 1 If the unit has no Ready indicator, use the time at which the power consumption level stabilizes to the Ready level, and note this detail when reporting the product test data.
- Steps 4 and 5 For products with more than one Sleep level, repeat these steps as many times as necessary to capture all successive Sleep levels and report this data. Two Sleep levels are typically used in large-format copiers and MFDs that use high-heat marking technologies. For products lacking this Mode, disregard Steps 4 and 5.
- Steps 4 and 6 Default-delay time measurements are to be measured in parallel fashion, cumulative from the start of Step 4. For example, a product set to enter a Sleep level in 15 minutes and enter a second Sleep level 30 minutes after entering the first Sleep level will have a 15-minute default-delay time to the first level and a 45 minute default-delay time to the second level.

**7.1.2 For the equipments follow Typical Energy Consumption (TEC) tests:** Measurement of TEC shall be conducted according to Table 7 for printers, fax machines, digital duplicators with print capability, and MFDs with print capability, and Table 8 for copiers, digital duplicators without print capability and MFDs without print capability, subject to the following provisions:

1) Paper: There shall be sufficient paper in the device to perform the specified print or copy jobs.

**2) Duplexing**: Products shall be tested in simplex mode. Originals for copying shall be simplex images.

**3)** Service/Maintenance Modes: Service/maintenance modes (including color calibration) should generally not be included in TEC measurements.

i) Any service/maintenance modes that occur during the test shall be noted.

ii) If a service/maintenance mode occurs during a job other than the first job, the results from the job with the service/maintenance mode may be replaced with results from a substitute job. In this case, the substitute job shall be inserted into the test procedure immediately following Job 4. The 15-minute job interval shall be maintained at all times.

4) Accuracy: The specifications of the metering equipment and ranges used in each measurement shall be reported. Measurements must be conducted so as to result in a total potential error of the TEC value of no more than 5%. Accuracy does not need to be reported for cases where the potential error is below 5%. When the potential measurement error is close to 5%, manufacturers should take measures to confirm that it complies with the 5% limit.

**5) Energy Measurement Method:** All measurements shall be recorded as accumulated energy over time, in watt-hours (Wh); all time shall be recorded in seconds or minutes.

(i) "Zero meter" references may be accomplished by recording the accumulated energy consumption at that time rather than literally zeroing the meter.

#### 6) Job Structure:

A) Jobs per Day: The number of jobs per day (N<sub>JOBS</sub>) is specified in Table 6.



Table 6: Number of Jobs per Day (N <sub>JOBS</sub> )			
Monochrome Product	Jobs per		
Speed, s	Day		
(ipm)	(Njobs)		
$s \le 8$	8		
8 < s < 32	S		
$s \ge 32$	32		

#### B) Images per Job:

1) Except for fax machines, the number of images shall be computed according to Equation 2, below. For convenience, Table 10 at the end of this document provides the resultant images per job computation for each integer product speed up through 100 images per minute (ipm).

#### **Equation 2: Calculation of Number of Images per Job**

 $N_{IMAGES} = int (0.5xs^2)$ N JOBS

Where:

- N<sub>IMAGES</sub> is the number of images per job, rounded down . (truncated) to the nearest integer,
- *s is the (monochrome) maximum reported speed in images per* minute (ipm), calculated in section 5.1.A), of this test procedure, and
- N<sub>JOBS</sub> is the number of jobs per day, as calculated per Table 6.
- C) Test Image: Test Pattern A from ISO/IEC standard 10561:1999 shall be used as the original image for all testing.
- 1) Test images shall be rendered in 10 point size in a fixed-width Courier font (or nearest equivalent)
- 2) German-specific characters need not be reproduced if the product is incapable of German character reproduction.
- D) Print Jobs: Print jobs for the test may be sent over non-network connections (eg., USB), even on those units that are network-connected.
  - 1) Each image in a print job shall be sent separately, i.e., all images may be part of the same document, but shall not be specified in the document as multiple copies of a single original image (unless the product is a digital duplicator).
  - 2) For printers and MFDs that can interpret a page description language (PDL) (e.g., PCL, Postscript), images shall be sent to the product in a PDL.

E) Copy Jobs:

1) For copiers with speed less than or equal to 20 ipm, there shall be one original per required image.



2) For copiers with speed greater than 20 ipm, it may not be possible to match the number of required original images (e.g., due to limits on document feeder capacity). In this case, it is permissible to make multiple copies of each original, and the number of originals shall be greater than or equal to ten.

**Example:** For a 50 ipm unit that requires 39 images per job, the test may be performed with four copies of 10 originals or three copies of 13 originals.

- 3) Originals may be placed in the document feeder before the test begins.
- i) Products without a document feeder may make all images off of a single original placed on the platen.

# Table 7: TEC Test Procedure for Printers, Fax Machines, Digital Duplicators with Print Capability, and MFDs with Print Capability

Step	Initial State	Action	Record (at end of step)	Unit of Measure	Possible States Measured
		Connect The Unit Under Test To The Meter. Ensure The Unit Is	Off energy	Watt-hours (Wh)	
1	Off	Powered And In Off Mode. Zero the meter, measure energy over 5 minutes or more. Record both energy and time.	Testing Interval time	Hours (h)	Off
2	Off	Turn on unit. Wait until unit indicates it is in Ready Mode.	-	-	-
3	Ready	Print a job of at least one output image but no more than a single job per Job Table. Measure and record time to first sheet exiting unit.	Active 0 time	Hours (h)	-
4	Ready (or other)	Wait until the meter shows that the unit has entered its final Sleep Mode or 4 hours.	-	-	-
5	Sleep	Zero meter; measure energy and time over 1 hour. Record the energy	Sleep energy, E <sub>SLEEP</sub>	Watt-hours (Wh)	Sleep
		and time.	Sleep time, $t_{SLEEP}$ ( $\leq 1$ hour)	Hours (h)	



6	Sleep	Zero meter and timer. Print one job (calculated above). Measure energy and time. Record time to first sheet exiting unit. Measure energy over 15 minutes from job initiation. The job must finish within the 15 minutes.	Job1 energy, E <sub>JOB1</sub> Active 1 time	Watt-hours (Wh) Hours (h)	Recovery, Active, Ready, Sleep
7	Ready (or other)	Repeat Step 6.	Job2 energy, E <sub>JOB2</sub> Active2 time	Watt-hours (Wh) Hours (h)	Same as above
8	Ready (or other)	Repeat Step 6 (without Active time measurement).	Job3 energy, E <sub>JOB3</sub>	Watt-hours (Wh)	Same as above
9	Ready (or other)	Repeat Step 6 (without Active time measurement).	Job4 energy, E <sub>JOB4</sub>	Watt-hours (Wh)	Same as above
10	Ready	Zero meter and timer. Measure energy and time until meter and/or unit shows that unit has entered Sleep Mode or the final Sleep Mode for units with multiple Sleep modes, or 4 hours.	$Final energy, E_{FINAL}$ Final time, $t_{FINAL}$	Watt-hours (Wh) Hours (h)	Ready, Sleep

Notes:

• Steps 4 and 10 – it may be unclear to independent testers which Sleep Mode is the final one and therefore a 4 hour time limit is provided.

# Table 8: TEC Test Procedure for Copiers, Digital Duplicators without PrintCapability, and MFDs without Print Capability

Step	Initial State	Action	Record (at end of step)	Unit of Measure	Possible States
					Measured
		Connect the unit under test to the	Off energy	Watt-hours	
		meter. Ensure the unit is powered		(Wh)	
1	Off	and in Off Mode. Zero the meter,	Testing		Off
		measure energy over 5 minutes or	Interval time	Hours (h)	
		more. Record both energy and time.			
		Turn on unit. Wait until unit has	-	-	-
2	Off	entered Ready Mode.			
		Copy a job of at least one image but	Active 0 time	Hours (h)	-



3	Ready	no more than a single job per Job			
		Table. Measure and record time to			
		first sheet exiting unit.			
		Wait until the meter shows that the	-	-	-
4	Ready	unit has entered its final Sleep Mode			
	(or other)	or 4 hours.		XX 7 1	
			Sleep energy	Watt-hours	
-	CI	Zero meter; measure energy and	<u></u>	(Wh)	GI
5	Sleep	time over 1 hour or until unit enters	Sleep time		Sleep
		Auto-Off Mode. Record the energy	$(\leq 1 \text{ hour})$	Hours (h)	
		and time.			
		Zero meter and timer. Copy one job	Johl anargy	Watt-hours	Dagovoru
		(calculated above). Measure and	Job1 energy,	(Wh)	Recovery,
6	Sleep	record energy and time to first sheet exiting unit. Measure energy over 15	Ejob1	( •• 11)	Active, Ready,
0	sieep	minutes from job initiation. The job	Active 1 time	Hours (h)	Sleep,
		must finish within the 15 minutes.	Active 1 time	fiburs (II)	Auto-off
		indst innsn within the 15 innutes.	Job2 energy,	Hours (h)	
7	Ready	Repeat Step 6.	EJOB2	iiouis (ii)	Same as
	(or other)		Active2 time	Watt-hours	above
				(Wh)	
8	Ready	Repeat Step 6 (without Active time	Job3 energy,	Watt-hours	Same as
	(or other)	measurement).	E <sub>JOB3</sub>	(Wh)	above
9	Ready	Repeat Step 6 (without Active time	Job4 energy,	Watt-hours	Same as
	(or other)	measurement).	E <sub>JOB4</sub>	(Wh)	above
		Zero meter and timer. Measure	Final energy,	Watt-hours	
10	Ready	energy and time until meter and/or	E <sub>FINAL</sub>	(Wh)	-
	(or other	unit shows that unit has entered its			Ready,
		Auto-off Mode or 4 hours. Record	Final time,	Hours (h)	Sleep
		energy and time; if unit began this	t <sub>FINAL</sub>		
		step already in Auto-off Mode,			
		report both energy and time values			
		as zero.	Auto aff		
11	A	Zono the metam measure and a little	Auto-off	W/att 1	Auto - ff
11	Auto-off	Zero the meter; measure energy and time over 5 minutes or more. Record	energy,	Watt-hours	Auto-off
			E <sub>AUTO</sub>	(Wh)	
		both energy and time	Auto-off	Hours (b)	
			time,	Hours (h)	
			t <sub>AUTO</sub>		

Notes:



• Steps 4 and 10 – it may be unclear to independent testers which Sleep Mode is the final one and therefore a 4 hour time limit is provided.



#### **APPENDIX B:**

# Format for reporting the test results

#### 1. Company Details

Applicant	Manufacturer	
Model No./Name	Model Family Name	

#### 2. Equipment Details

Product Type (tick whichever applicable)	Printer
(lick whenever applicable)	Scanners
	Copiers
	Fax Machines
	Multi Function Device
Marking Technology (tick whichever applicable)	
	Dye Sublimation (DS)
	Electro-Photographic (EP)
	Impact
	Ink Jet (IJ)
	High Performance IJ
	Solid Ink (SI)
	Thermal Transfer (TT)
Media Format (tick whichever applicable)	Large Format
	Standard Format
	Small Format
P <sub>READY</sub> (W)	
P <sub>SLEEP</sub> (W)	
P <sub>AUTO-OFF</sub> (W)	
P <sub>OFF</sub> (W)	
Standby Mode Power Consumption	
(Lowest of the above power modes) for	
OM products	
Typical Energy Consumption for TEC products	

Summary

Declaration:

Name Date:



#### <u>Annexure - I</u>

#### Label Design and Manner of Display

#### 8. Material and Shape:

The label shall be self-adhesive if it has to be pasted on the appliance. If the label is to be attached as a swing tag, then it shall be made of durable cardboard. The design of the label shall be as given in the following figure. The label design in .cdr (corel draw) format can be downloaded from BEE's website for accurate design and colour scheme.

